


R04 PAGE 1 OF 50











FIGURE 2B


FIGURE 3B














R04 PAGE 2 OF 50







R04 PAGE 4 OF 50





R04 PAGE 5 OF 50




R04














FIGURE 9



FIGURE 10A





R04 PAGE 11 OF 50



FIGURE 10 C




FIGURE 10 A1







FIGURE 10 B1



R04







FIGURE 11 Safety Zones



PAGE 16 OF 50 R04

FIGURE 12 A

es Patent Office. Drawings. Continuation in Part 4 - Rajasingh







FIGURE 12 B






FIGURE 12 C





FIGURE 12 A1



R04 PAGE 20 OF 50




FIGURE 12 C1







FIGURE 12 D 1














FIGURE 12 H2





nuary 2001.








FIGURE 13

AN ISOMETRIC VIEW










R04 PAGE 30 OF 50



FIGURE 15 A










FIGURE 15 C






FIGURE 16 A



R04 PAGE 34 OF 50

FIGURE 16 B



PAGE 36 OF 50

R04



FIGURE 16D










FIGURE 17 A and B








R04 PAGE 39 OF 50















FIGURE 18 H











FIGURE 18 J






FIGURE 19 A







FIGURE 19 B
















FIGURE 20 A



R04

FIGURE 20C



R04 PAGE 49 OF 50

FIGURE 20 B

